



ASSEMBLY INSTRUCTIONS

X A HOWARD MILLER COMPANY

25604 - END TABLE WITH DRAWER

NO.	Hardware List		Q'ty
A	() mmmmm	Bolt 5/16" * 80mm L	4
В	8	Lock Washer 5/16"Dia	4
С	0	Flat Washer 5/16" Dia	4
D		Wrench 3/16"Dia*4-3/4"L	1







PLACE THE TABLE UPSIDE DOWN ON SOFT AND CLEAN SURFACE TO PREVENT SCRATCHING

- 1. ATTACH THE FOUR LEGS (#1) TO THE TABLE TOP
- 2. ASSEMBLE THE STRETCHER TO THE FOUR LEGS WITH BOLT (A), LOCK WASHER (B), AND FLAT WASHER (C) BY USING WRENCH (D)
- 4. SET THE TABLE UPRIGHT, ASSEMBLY COMPLETE

MADE IN INDONESIA